



Tech Tips

TT 21-00-17

Date: 2000

1999 and 2000 Golf, Jetta and New Beetle 1.8L Turbo - Engine Stalls

DTC 1557 (17965) Charge Pressure Control Positive Deviation can be caused by a defective re-circulation valve for turbo boost, causing the fuel trim to go to rich. Replace the re-circulation valve for turbo boost to correct this fault.