



Tech Tips

TT 17-06-04

Date: 2006

Vehicles with 1.8 Turbo Engine, Oil Pan Replacement

After ordering a replacement engine, you may find that the oil pan on the remanufactured engine has an oil level sensor, but the original did not. The dealer should leave the oil pan (with the sensor) installed on the remanufactured engine and NOT change it. If, however, the original oil pan had an oil level sensor and the remanufactured engine does not, the original oil pan (with the sensor) must then be installed. The following photos show the two types of oil pans (with and without the sensor).



Oil Pan Without Sensor



Oil Pan With Sensor