



Tech Tips

TT 24-00-29

Date: 2000

Models With Snow Screen, Fuel Trim Faults

When diagnosing a fuel trim fault, check the intake box air duct for a snow screen. This screen can become clogged and can contribute to these faults. This screen must not be removed.