



# Tech Tips

**TT 24-99-33**

**Date: 1999**

## **1996> OBD II Vehicles, Basic Settings - Throttle Valve Control Module**

When performing basic settings, throttle valve control module (04-098-04-060), it is important to stay in the program for 30 seconds. Exiting the program prior to 30 seconds could cause the basic settings not to set.